

Piracy Alert Gulf of Guinea

- update -



Our circular published in May 2020 promoted the awareness about the dangers and risks associated with piracy in the Gulf of Guinea. Since our last circular, we have seen a significant increase in the number of violent attacks, some of which resulted in the loss of lives of seafarers.

With this updated circular, MS Amlin wishes to alert shipowners and charterers about the dangers of piracy in the Gulf of Guinea by providing information and practical recommendations.

Gulf of Guinea

According to the recent annual report of the International Maritime Bureau's Piracy Reporting Centre (IMB), the Gulf of Guinea hit a record with 130 crew kidnappings in 22 separate incidents in 2020 (source: ICC Commercial Crime Services). About 95% of all reported maritime kidnapping cases worldwide have taken place in the Gulf of Guinea. Unfortunately, the first months of 2021 do not show any signs of improvement. Already in January several notable attacks and violent kidnappings were reported.

The IMB report notes that incidents in the Gulf of Guinea are particularly dangerous as the majority of the perpetrators were equipped with guns. Until a couple of years ago cargo theft seemed to be the main driver for piracy, but nowadays we are seeing a shift towards violent kidnapping of crew members with the objective to demand a ransom. The kidnapped crew members are consequently taken deep into the jungle where they are held hostage for months until ransom is paid. The conditions in the camps are severe, resulting in sickness or sometimes even death.

The issue of piracy in the Gulf of Guinea used to be significantly different from, for example, the Horn of Africa, where most attacks take place in international waters where vessels can be protected by the international community. Within the Gulf of Guinea, however, many attacks occur near the coast and the responsibility to deal with an act of piracy within territorial waters rests with the coastal state. Previous years have shown that the pirates are now able to operate further from shore, as incidents have been reported to take place at 200 nautical miles from the coastline. As a result, the international community has been alerted and initiatives to protect vessels have been initiated such as, for example, the pilot case of the EU's Coordinated Maritime Presences (CMP) concept (source: European Council).



Precautionary measures

MS Amlin advises ship operators, masters and mariners to remain vigilant and stay cautious when operating in the Gulf of Guinea. As the subject matter is far too extensive to be covered in full within this circular, we recommend following and implementing the Best Management Practices for West Africa (BMP-WA), which aim to help ships plan their voyage and to detect, avoid and report attacks. These can be found <a href="https://example.com/here/

In summary, the following precautionary measures should be taken.

· Voyage planning and risk assessment

It is essential that a detailed security assessment is completed before each voyage to or within the region. A security assessment should include at least:

- The IMB advises ship operators to stay at least 250 nm offshore in West Africa and wait until a safe anchorage or dock is available to load and unload cargo.
- The ship's characteristics/vulnerabilities/inherent capabilities to withstand the threat.
- The ship's and company's procedures (drills, watch rosters, chain of command, decision making processes etc.).
- Availability of Secure Anchorage Areas (SAA),
 Security Escort Vessels (SEV) and co-operation with military.

Crew training

Crew members should be made aware of the threats, risks and consequences of the voyage in any risk area. Before departure, the crew should be briefed on how to implement and use the vessel protection measures. In addition, regular drills should be conducted as training in a safe environment gives crew members valuable hands on experience and the confidence needed in a real emergency.

Information security

In order to prevent information about the vessel, her location, cargo and crew from falling into the wrong hands, communication with external parties should be kept to a minimum. The crew should be reminded of the dangers of posting voyage related information on social media.

Vessel protection measures

The BMP-WA contains very detailed guidance on vessel protection measures against attacks. It is recommended that the following measures are implemented or installed on board the vessel:

- A proper lookout can help to identify any threats at an early stage, allowing the crew to deploy other defences in good time.
- Physical barriers, such as razor wire, which prevents persons from boarding the vessel.

- Water or foam spray, which delays people in their attempt to board the vessel.
- Enhanced bridge protection, such as bars, steel plates and blast resistant film on windows, which reduces the risk of injury to the crew due to fragmentation.
- Citadel and safe muster points for the crew.

"The Gulf of Guinea accounts for over 95% of global crew kidnappings"

Privately armed security personnel

The last decade demonstrated that the use of Privately Contracted Armed Security Personnel (PCASP) on board vessels has proven to be an effective measure in protecting the safety of seafarers and deferring attacks from pirates in high risk areas. Nevertheless, the decision to deploy PCASP's should not be treated lightly and will be guided by certain requirements.

Unlike the Somalian pirate attacks in the Indian Ocean, the attacks in the Gulf of Guinea often take place on vessels entering or leaving ports, or at anchor within the territorial waters. National laws of these coastal states do not permit foreign security guards to carry firearms on board merchant vessels. Therefore, shipowners must rely on local security force, for example the local navy forces. If a shipowner wishes to have armed guards on board his vessel in an area which does not allow PCASP, all non-local armed guards must disembark the vessel and be replaced with local security personnel when the vessel is entering territorial waters. To make use of such local security guards, a shipowner can either rely on a local agent with direct links to the military or police within that country, or engage the services of an intermediary.

The carriage of firearms is a complex legal issue and is still prohibited by some flag states, although a number of flag states are in the process of amending their laws in order to allow the practice of PCASP on board vessels. MS Amlin neither dismisses nor promotes the use of services of PCASP, but would rather emphasise that the decision whether to resort to the services of such companies lies solely with the shipowner. Accordingly, we recommend shipowners to consult their flag states when considering the services of PCASP, as well as contacting the coastal states of the territorial waters to be entered before embarking on the voyage.

Contracts and clauses

In order to protect the contractual position of shipowners with regards to voyages going through or to a high risk area, we advise incorporating specific "piracy clauses" in charter parties.

BIMCO has created specialist Piracy Clauses for time charter parties, consecutive voyage charters/COAs, and single voyage charters. These clauses allow shipowners to deviate from the contractual voyage, as they are not obliged to continue to or through any port, place, area or zone which, in the reasonable judgment of the master/owner, is dangerous due to any actual, threatened or reported piracy or violent robbery. In the event that the vessel is at a location that meanwhile becomes dangerous, the vessel shall be at liberty to leave it.

Where Privately Contracted Armed Security Personnel are employed on board a vessel, we recommend the use of contracts recognised by the industry, such as the GUARDCON, which can be found on the website of BIMCO via this <u>link</u> or requested from our Client Services Desk.

Conclusion and recommendations

In principle, all states have universal jurisdiction on the high seas and are thus allowed to seize pirate ships and arrest pirates on board. However, the same does not apply to piracy within territorial waters where the coastal state has exclusive jurisdiction.

This region of West Africa remains a high risk area and there is still a long way to go before a satisfactory state of security can be established. Protection by local law enforcement, such as naval forces, remains limited and assistance is not always available. Therefore, it is of utmost importance that shipowners take precautionary measures to protect their vessels and their crew when transiting through the Gulf of Guinea. Consequently, we advise shipowners to closely follow the Best Management Practices for West Africa.

Furthermore, the use of PCASP has been effective but not always allowed under both flag state and coastal state law. Therefore, approval from the authorities has to be obtained before entering the area.



"It is of utmost importance that shipowners take precautionary measures to protect their vessels and their crew when transiting through the Gulf of Guinea."

Useful websites

More information about piracy in the Gulf of Guinea can be found on the following websites.

- ► IMB Annual piracy report
- Privately armed security personnel on the website of the IMO
- ► Best Management Practices West Africa (BMP-WA)
- ▶ EU Maritime Security Factsheet: The Gulf of Guinea
- Maritime Security and Piracy IMO
- ► Maritime Domain Awareness for Trade-Gulf of Guinea (MDAT-GoG)
- ► International Maritime Piracy Reporting Center
- ► Gulf of Guinea Inter-Regional Network (GoGIN)
- ► Global Counter Piracy Guidance for Companies, Masters and Seafarers (GCPG)
- ► <u>BIMCO</u> (members only)

This information is meant for guidance only. Should you require more information or assistance, please feel free to contact our Client Services Desk: ClientServicesDesk@msamlin.com



Pieterjan Brands Information Officer Pieterjan.Brands@msamlin.com



Sonja van Wijk Senior Client Advisor Sonja.VanWijk@msamlin.com



MS Amlin Marine N.V.

Postal Address: P.O.Box 30152, 3001 DD Rotterdam

Visiting Address: Beursplein 37, 3011 AA Rotterdam

The Netherlands Tel: +31 10 799 5800

msamlin.com

MS Amlin offices

London, Paris, Antwerp, Rotterdam, Hamburg, Dubai and Singapore

© February 2021. The information contained herein is intended to be for informational purposes only and is correct at the time of printing. This brochure is not, and is not intended to be construed as, an offering of MS Amlin securities in the United States or in any other jurisdictions where such offers may be unlawful. The services and products mentioned in this brochure may not be available in the United States or in jurisdictions where Lloyd's does not have a trading license. Potential insureds should consult with an appropriately licensed broker in their area for further information. MS Amlin Underwriting Limited is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority under reference number 204918. Registered office The Leadenhall Building, 122 Leadenhall Street, London EC3V 4AG. Registered in England Company No. 02323018. MS Amlin Marine N.V. is registered in Belgium no. 0670.726.393. Registered address: office is Koning Albert II-laan 37, 1030, Brussels, Belgium. MS Amlin (MENA) Limited is regulated by the Dubai Financial Services Authority (DFSA). MS Amlin (MENA) Limited may only undertake the financial services activities that fall within the scope of its existing DFSA licence. MS Amlin (MENA) Limited is principal place of business in the DIFC is MS Amlin (MENA). Limited, Level 3, Precinct Building 2, Dubai International Financial Centre, Dubai, United Arab Emirates. P.O. Box 506929. This document is intended for Professional clients only as defined by the DFSA and no other person should act upon it.MS Amlin Asia Pacific Pte Limited is approved by the Monetary Authority of Singapore to underwrite on behalf of the members of Syndicate 2001 at Lloyd's. Registered in Singapore No. 200711910C Registered office 138 Market Street #03-01 CapitaGreen Singapore 048946.